



दिल्ली सरकार

लोक निर्माण विभाग,  
(दिल्ली सरकार)

कार्यालय कार्यपालक अभियंता  
उत्तर पश्चिम भवन ।

राजकीय उच्चतर माध्यमिक विद्यालय प्रांगण,  
एस.यू. ब्लॉक, पीतमपुरा दिल्ली-110034

Email: [eepwddelhim342@gmail.com](mailto:eepwddelhim342@gmail.com)



Government of India

संख्या:- 23(Lakshmibai College)/का0अभि0/उ.प. ग.-1/ दिनांक:- 4/10/2020

सेवा में,

**The Principal**

Lakshmi Bai College

Ashok Vihar-III, New Delhi-110052


**Sub:- Structural Audit to make building seismically complaint in respect of Property No. Lakshmi Bai College, Ashok Vihar, Ph-III, Delhi.**

**Ref:- Your letter No. LBC/1383/2020 dated 05.10.2020**

Madam,

Kindly refer the above letter vide which the structural safety certificate is requested from this office. The building was inspected alongwith your goodself and concerned Assistant Engineer on 09.10.2020. It is observed that all the blocks are safe only the projected portion of old building are observed falling of concrete with plaster. This can be retro-fitted and rehabilitated with suggestion of experts in this field. The overall building is safe for use.

Submitted for your kind information.

  
श्री केशव राम  
कार्यपालक अभियंता  
लो0नि0वि0 मंडल उ0प0 भवन-1  
एस यू ब्लॉक, पीतमपुरा दिल्ली ।

प्रतिलिपि:-

1. The Assistant Engineer N-W B-15, Ashok Vihar Delhi. You are hereby directed to submit the Preliminary Estimate for Retro-fitting of projected chajjas and other areas so that same can be repaired immediately.

कार्यपालक अभियंता